

PASS

Test location

Expiry date

12 September 2025[▶ View test location](#)

Monitor and repair if necessary (advisories):

- **Nearside Front Vehicle structure is repaired but structural rigidity is not significantly reduced repairs covered with underseal (6.1.1 (d) (i))**
- **Offside Front Vehicle structure is repaired but structural rigidity is not significantly reduced jacking point repairs covered with underseal (6.1.1 (d) (i))**
- **Nearside Front Inner Vehicle structure is corroded but structural rigidity is not significantly reduced above driveshaft (6.1.1 (c) (i))**

[▶ What are advisories?](#)

Date tested

13 September 2024

FAIL

Mileage

56,362 miles

MOT test number

[1997 4009 1789](#)

Test location

[▶ View test location](#)

Repair immediately (major defects):

- **Offside Front Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting very front near abs mount (6.2.2 (d) (i))**
- **Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced by jacking point (6.1.1 (c) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Inner Vehicle structure is corroded but structural rigidity is not significantly reduced above drive shaft (6.1.1 (c) (i))**

[▶ What are defects and advisories?](#)