


NUOVO DUCATO X250 2.2 JTD FRONT LIGHT CLUSTER MOULDING.FRAME (ONE) LH OR RH R R 7055A65


[back to WINDSCREEN WIPER ASSEMBLY - R+R OR REPAIR](#)



Removing ([Refitting](#))

- Open the bonnet.

1. Undo the bolts (1a) securing the lamp upper moulding (1b).



1. Release the retaining pin (1a) and remove the lamp upper moulding (1b) from the vehicle.

Refitting ([Removing](#))

- Check that the lamp upper moulding is not damaged.
- Place the lamp upper moulding in position fitting the retaining pin.
- Tighten the bolts fixing the lamp upper moulding.